


TRANSSTEEL 3000C PULSE

Quick Guide to Synergic Welding



1 Set the welding process



MANUAL The parameters for the welding power can be set individually.


STD SYNERGIC When setting a welding power parameter, the remaining parameters are set automatically.

PULSE SYNERGIC automatically.

Manual metal arc welding

TIG welding

4 Set the welding power




> select desired parameter


set desired parameter

2 Set the filler metal and shielding gas

	Steel/ER 70-120	inch	mm	
2	CrNi/Stainless	.030	0,8	
3	CuSi/ER CuSi-A	.035	0,9	CO ₂ 100% A
4	AlMg/ER 5xxx	.040	1,0	Ar + 2-12% CO ₂ B
5	AlSi/ER 4xxx	.045	1,2	Ar + 13-25% CO ₂ C
6	Metal Cored	.052	1,4	Ar + 2-8% O ₂ D
7	Self-shielded	1/16	1,6	Ar 100% E
8	SP	SP	SP	SP F



5 Set the correction parameters




< select desired parameter

set desired parameter

Measuring the welding circuit resistance r

According to the Operating Instructions of the power source



Activating/deactivating the key lock

EasyJobs



1x Retrieve:

Save:

Delete:



42,0426,0369,EA

001-01072020

Operating Instructions:
www.fronius.com/transsteel




TRANSSTEEL 3000C PULSE

Description of Setup Parameters




MIG/MAG Synergic Setup menu



- [1] Press and hold
- [2] Press

GPr Gas pre-flow time
GPo Gas post-flow time
SL Slope (2-step, special 4-step)
I-5 Starting current (2-step, special 4-step)
I-E Final current (2-step, special 4-step)
t-5 Starting current duration (2-step)
t-E Final current duration (2-step)
Fd Feeder inching speed
bbC Burnback effect
tfo Length of wire fed before the safety cut-out trips
SPt Spot welding time / interval welding time
SPb Interval pause time
Int Interval
FRC Reset power source to factory settings
2nd 2nd menu level
SET Country-specific setting (metric/imperial)
Syn Synergic characteristics (EUR/US)
C-C Cooling unit control
C-t Cooling unit monitoring
r Welding circuit resistance
L Welding circuit inductivity
EnE Electrical energy of the arc
RLC Arc length correction via [V]


MIG/MAG Manual Setup menu



- [1] Press and hold
- [2] Press

GPr Gas pre-flow time
GPo Gas post-flow time
Fd Feeder inching speed
bbC Burnback effect
IGC Ignition current
tfo Length of wire fed before the safety cut-out trips
SPt Spot welding time / interval welding time
SPb Interval pause time
Int Interval
FRC Reset power source to factory settings
2nd 2nd menu level
SET Country-specific setting (metric/imperial)
C-C Cooling unit control
C-t Cooling unit monitoring
r Welding circuit resistance
L Welding circuit inductivity
EnE Electrical energy of the arc

Exiting the Setup menu




Rod electrode Setup menu



- [1] Press and hold
- [2] Press

HCU HotStart current
He Hot current time
ASL Anti-stick
FRC Reset power source to factory settings
2nd 2nd menu level
SET Country-specific setting (metric/imperial)
r Welding circuit resistance
L Welding circuit inductivity

TIG Setup menu



- [1] Press and hold
- [2] Press

F-P Pulse frequency
Up UpSlope
do DownSlope
I-5 Starting current
I-2 Lowering current
I-E Final current
GPo Gas post-flow time
ERC Tacking
FRC Reset power source to factory settings

2nd 2nd menu level
SET Country-specific setting (metric/imperial)
C-C Cooling unit control
C-t Cooling unit monitoring

SAFETY

Before working with the device, ensure that you have read and understood all the documents provided in hard copy and online. This document does not describe all the functions of the device. For a complete description of the device, refer to the Operating Instructions.

