

7/16 Reliance Drive Tuggerah NSW 2259

Tel: Int'l +61(02) 9476 4544 •• E-mail: [kelba@kelba.com](mailto:kelba@kelba.com) • Web Site: [www.kelba.com](http://www.kelba.com)

## Kelba BHW Dynamometer with Wireless Remote Display

### Description


A/D conversion method :

$\Sigma$ - $\Delta$  24bit

Working Frequency:

Range:

Power supply:



CAP./SIZE	A	A1	B	W	Φ
1~5t	230	160	76	34	28
7.5t/10t/15t	280	180	90	47	40
20~30t	370	230	125	55	53
40~60t	430	260	150	65/85	73
100~150t	570	340	210	108	102

7/16 Reliance Drive Tuggerah NSW 2259

Tel: Int'l +61(02) 9476 4544 •• E-mail: [kelba@kelba.com](mailto:kelba@kelba.com) • Web Site: [www.kelba.com](http://www.kelba.com)

## Features

✚ Wireless operation up to 200 meters	✚ Light weight Aluminium housing
✚ Remote hand held LCD display with 18mm 6 digits with backlighting	✚ 26mm through top and bottom hole for attaching shackles or hooks
✚ Indicator fitted with Lithium batteries	✚ 3 x AA / 1.5 V Alkaline batteries power supply
✚ Portable Tension & Force weighing	
✚ Capacities from 1000kg to 150000kg	

## Specifications

Model	Capacity	LCD Display	Unit Weight	Shipping Weight

Maximum Safe Load:	150% Full Scale.
Ultimate Overload Capacity	150% Full Scale.
Zero Range	100% Full Scale.
Tare Range:	0 to 100%.
A/D conversion method	$\Sigma$ - $\Delta$ 24bit
Power Supply:	3 x AA / 1.5 V Alkaline batteries.
Battery life @ new	24 hours without backlighting using Four AA / 1.5 V Alkaline batteries.
Finish:	Aluminium alloy housing.
Operating Temperatures:	-20 degrees C ~ + 45 degrees C.
Operating Humidity:	<90% RH.
Display reading:	6 Digit 18mm display with back light.
Auto Shut Off:	Yes, 30 minutes after the scale has been inactive or at extremely low power.