


# Sweeper Service Checklist

<b>CUSTOMER:</b>				<b>SITE CONTACT:</b>			
<b>DATE: 23/8/24</b>		<b>MODEL: PB110E</b>		<b>SERIAL NO: 10566</b>		<b>UNIT HOURS: 1036.5</b>	
<b>Conduct a full function test</b>							
Check Drive System			Check All Controls & E/S switches			Check Sweeping System & Hopper Function	
<b>Battery Condition and charger</b>							
<b>System Voltage: VDC</b>		<b>Tested: VDC</b>		<b>Charger output: VDC</b>		<b>Cables, Lugs and connections</b>	
						<b>Good</b>	Repaired
<b>Battery 1 Hydrometer reading</b>	<b>Cell 1</b>	<b>Cell 2</b>	<b>Cell 3</b>	<b>Cell 4</b>	<b>Cell 5</b>	<b>Cell 6</b>	
Battery 2 Hydrometer reading							
Battery 3 Hydrometer reading							
Battery 4 Hydrometer reading							
Battery 5 Hydrometer reading							
Battery 6 Hydrometer reading							
<b>Check Sweeping System</b>							
<b>Main Broom Condition</b>	Good	Replaced	Required	<b>Main Broom Bearing</b>	Good	Replaced	Required
<b>Side Broom Condition</b>	Good	Replaced	Required	<b>Skirting &amp; Dust Seals</b>	Good	Replaced	Required
<b>Brush Pressure</b>	Good	Adjusted	Required	<b>Clean Hopper Filter</b>	Good	Repaired	Required
<b>Check Vacuum System</b>	Good	Repaired	Required	<b>Drive Motors &amp; Belts</b>	Good	Replaced	Required
<b>Service Engine &amp; Auxiliary</b>							
<b>Engine Oil &amp; Filter</b>	Good	Replaced	Required	<b>Engine Air Filter</b>	Good	Replaced	Required
<b>Belt &amp; Cooling System</b>	Good	Replaced	Required	<b>Fuel system &amp; Filter</b>	Good	Replaced	Required
<b>Spark Plug/s</b>	Good	Replaced	Required	<b>Hydraulic Oil Filter/s</b>	Good	Replaced	Required
<b>Check Drive System</b>							
<b>Drive motor/s</b>	Good	Repaired	Required	<b>Drive wheel/s</b>	Good	Repaired	Required
<b>Steering Linkages</b>	Good	Repaired	Required	<b>Braking system</b>	Good	Repaired	Required
<b>Check Controls &amp; safety Switches</b>							
<b>Dash Display</b>	Good	Repaired	Required	<b>Ignition Switch</b>	Good	Repaired	Required
<b>Lighting and beacon</b>	Good	Repaired	Required	<b>E/stop switches</b>	Good	Repaired	Required
<b>Reverse Beeper</b>	Good	Repaired	Required	<b>Horn</b>	Good	Repaired	Required
<b>Wash down/ clean machine</b>						<b>Customer Feedback</b>	
<p><b>Comments</b></p> <p>Machine requires headlights, drive belts, steering column plastic trim, side broom arm straightened, batteries, handbrake cable, beacon light bulb panel filter, main broom, side broom &amp; hopper flaps.</p> <p>Machine also requires rust removal &amp; paint.</p>							
<b>Technicians Name: Paolo Duru</b>						<b>PD</b>	

1800 826 789 [conquestequipment.com.au](http://conquestequipment.com.au)

ABN: 94 151 697 862

**MELBOURNE**  
32 Global Drive  
Tullamarine VIC 3043  
[melbourne@conquestequipment.com.au](mailto:melbourne@conquestequipment.com.au)

**SYDNEY**  
1/11 Lagana Place  
Wetherill Park NSW 2164  
[sydney@conquestequipment.com.au](mailto:sydney@conquestequipment.com.au)

**BRISBANE**  
55 Millennium Place  
Tingalpa QLD 4173  
[brisbane@conquestequipment.com.au](mailto:brisbane@conquestequipment.com.au)

**SHEPPARTON**  
12 Telford Drive  
Shepparton VIC 3630  
[sales@conquestequipment.com.au](mailto:sales@conquestequipment.com.au)