


Sweeper Service Checklist

CUSTOMER:				SITE CONTACT:				
DATE: 26/08/24		MODEL: PB160LPG		SERIAL NO: 6461		UNIT HOURS: 452.6		
Conduct a full function test								
Check Drive System			Check All Controls & E/S switches			Check Sweeping System & Hopper Function		
Battery Condition and charger								
System Voltage: VDC		Tested: VDC		Charger output: VDC		Cables, Lugs and connections		
						Good	Repaired	Required
Battery 1 Hydrometer reading	Cell 1	Cell 2	Cell 3	Cell 4	Cell 5	Cell 6		
Battery 2 Hydrometer reading								
Battery 3 Hydrometer reading								
Battery 4 Hydrometer reading								
Battery 5 Hydrometer reading								
Battery 6 Hydrometer reading								
Check Sweeping System								
Main Broom Condition	Good	Replaced	Required	Main Broom Bearing	Good	Replaced	Required	
Side Broom Condition	Good	Replaced	Required	Skirting & Dust Seals	Good	Replaced	Required	
Brush Pressure	Good	Adjusted	Required	Clean Hopper Filter	Good	Repaired	Required	
Check Vacuum System	Good	Repaired	Required	Drive Motors & Belts	Good	Replaced	Required	
Service Engine & Auxiliary								
Engine Oil & Filter	Good	Replaced	Required	Engine Air Filter	Good	Replaced	Required	
Belt & Cooling System	Good	Replaced	Required	Fuel system & Filter	Good	Replaced	Required	
Spark Plug/s	Good	Replaced	Required	Hydraulic Oil Filter/s	Good	Replaced	Required	
Check Drive System								
Drive motor/s	Good	Repaired	Required	Drive wheel/s	Good	Repaired	Required	
Steering Linkages	Good	Repaired	Required	Braking system	Good	Repaired	Required	
Check Controls & safety Switches								
Dash Display	Good	Repaired	Required	Ignition Switch	Good	Repaired	Required	
Lighting and beacon	Good	Repaired	Required	E/stop switches	Good	Repaired	Required	
Reverse Beeper	Good	Repaired	Required	Horn	Good	Repaired	Required	
Wash down/ clean machine						Customer Feedback		
Comments <ul style="list-style-type: none"> - Machine requires an engine service, brake pedal adjustment, seat switch install, brake switch needs attention, needs front/left/rear dust flaps, hopper door flap, pre-filter, new rear wheel, main broom bearings, main broom & side broom - The body needs some attention as there is notable rust on most panels 								
Technicians Name: Paolo Duru						PD		

1800 826 789 conquestequipment.com.au

ABN: 94 151 697 862

MELBOURNE
32 Global Drive
Tullamarine VIC 3043
melbourne@conquestequipment.com.au

SYDNEY
1/11 Lagana Place
Wetherill Park NSW 2164
sydney@conquestequipment.com.au

BRISBANE
55 Millennium Place
Tingalpa QLD 4173
brisbane@conquestequipment.com.au

SHEPPARTON
12 Telford Drive
Shepparton VIC 3630
sales@conquestequipment.com.au